




Figure 1



↓ Compression molding



↓ Consolidating



↘ Irradiate and Melt Then Machine for Final Shape.

Figure 2




Figure 3




Figure 4




Figure 5




Figure 6 :




Figure 7:




Figure 8:





Figure 9:



10/318567

Figure 10:

